# M series HMI table

PLC export process

1.Create variable and assign the address, click the HMI symbols

2.Choose the HMI series then compile then generate the HMI symbol table


3.Select the path to save the table

HMI import

1.device setting

2.Address Import:

3.After import you can choose to delete or keep the current variable

4.Newly added tag can be checked

5.How to use the tag: